Financial Bid .		Annexure-A				
S.No.	ITEMS IN FIRE FIGHTING WATER SUPPLY SYSTEM	UNIT	QTY.	Rate (Rs)	Amount (Rs)	
1	Supply and Fixing of Pressure gauge (dial type) Range 0-12 kg/cm2 make H Guru, dial size-100mm	No.	7			
2	Supply and Fixing of Pressure switch, 230v, range 0 -10 kg/cm2, differntial pressure 07-4 kg/cm2, make Danfoss/Indfoss Including wiring	No	10			
3	Supply and Fixing of 250 mm dia MS pipe (class C) header line with ISI marked with CML No . The jointing should be seamless welded . With Wrapping coating - Underground pipes .Complete in all respect	mtr.	12	,		
4	Supply and Fixing of 250 mm dia MS pipe (class C) header line with ISI marked with CML No . The jointing should be seamless welded . With Post office red paint and Primer - Over ground work .Complete in all respect	mtr.	12			
5	Supply and Fixing of 150 mm dia MS pipe (class C) header line ISI marked with CML No . The jointing should be seamless welded underground piping. With wrapping coating primer.	mtr.	10			
6	Supply and Fixing of 150 mm dia MS pipe (class C) header line ISI marked with CML No . The jointing should be seamless welded Overground work -With Post Office RED paint and primer.	mtr.	12			
7	Supply and Fixing of 100 mm MS pipe (classC) header line with ISI marked & CML No . The jointing should be seamless welded - underground piping -with Wrapping Coating	mtr.	12		,	
8	Supply and Fixing of 100 mm MS pipe (class C) header line with ISI marked & CML No . The jointing should be seamless welded - Over ground piping - Post office Red paint and primer	mtr.	12	r		

			·		
9	Supply and Fixing of Sprinkler Control valve fixed on 150mm pipe line make HD	No	1	-	
10	Supply and fixing of Pressure vessel -(Cylinderical) -Made of MS 8mm sheet, height 1800 mm, dia 450mm-with Primer & Post Office Red paint-Complete in all Respect.	No	1		
11	Supply and fixing of Rubberwasher for female coupling of Hydrant valve 63mm dia.	No	120		2
12	Repair of Monoblock pump set capacity 7.5 HP, 2800 RPM, Make Kirloskar. The work includes replacement of Bearings, seal, etc. Any shaft turning work. Refitting. Complete in all respect in fully functional condition. There should not be any leakage or unusual sound on full pressure	No.	2		
13	Monoblock pump set capacity 10 HP, 2800 RPM, Make KirloskarThe works includes replacement of Bearings , seal . Any shaft turning work . Refitting . Complete in all respect in fully functional condition . There should not be any leage or unusual sound /vibration on full pressure	5	1		
14	Supply and fixing of CI Non Return valve -both end Flanged dia 100mm make Saint/kirloskar preferably ISI marked	No.	6	•	
15	Supply and fixing of Fire Box Glasses- with fixing and Rubber beeding. (Size of the glass is 560 mmx380mmx5mm . The work includes rounding of the glass and cut to size).	No	20		
16	Supply and fixing of Ball valve 25mm-(Brass make Zoloto)	No.	10	×.	
17	Supply and Fixing of Ball valve-10 mm - (Brass make Zoloto )	No.	6		
18	Supply & fixing of Butterfly valve: 80mm, as per IS 13095with CML No body CI GG25, disc SGI GGG40 Stem: AISI 410 Liner EPDM working pressure PN1.6 make zoloto/Audco	No	6		

					В
19	Ovehauling of sluice valves including checking leakage through stuffing box & side flanged gasket . Noise/Vibration while opening & closing . Condition of spindle , spindle nut & yoke sleeve thread , replacing damaged parts in fully functional condition -200 mm	No	1		
20	Ovehauling of sluice valves including checking leakage through stuffing box & side flanged gasket . Noise/Vibration while opening & closing . Condition of spindle , spindle nut & yoke sleeve thread , replacing damaged parts in fully functional condition -150 mm	No	4		
21	Ovehauling of sluice valves including checking leakage through stuffing box & side flanged gasket . Noise/Vibration while opening & closing . Condition of spindle , spindle nut & yoke sleeve thread , replacing damaged parts in fully functional condition -100 mm	No	11		
22	Ovehauling of sluice valves including checking leakage through stuffing box & side flanged gasket . Noise/Vibration while opening & closing . Condition of spindle , spindle nut & yoke sleeve thread , replacing damaged parts in fully functional condition -80 mm	No	1		
23	Fire Sprinkler Pendent type -Temp. rating-155F/68C-make Tyco	No	20	,	

Total Amount in words (Excluding GST) :-

1.In case of any descripancy in words and figures in the quoted amount , higher of the two would be considered

2. GST is excluded. Hence would be paid extra

0

Total Amount in figures (Excluding GST)